

HIGHWAY FACTORS AND RAILROAD GRADE CROSSING GROUP CHAIRMAN'S FACTUAL REPORT

Highway and Rail Crossing Attachment – Buckingham Branch Railroad – Grade Crossing Warning System, Electro-Mechanical Relay Test Records

Crozet, Virginia

HWY18MH005

(2 pages)

4 YEAR



Result/Condition Left Codes

A - Adjustments made, test completed and left in compliance (item shall be identified)
R - Replacement made, test completed and left in compliance (item shall be identified)

C - Test Completed, left in compliance

TRAIN CONTROL RELAY TEST

FRA RULES 234.263,236.105, 236.106(a),236.106(b),236.106(c)

LOCATION:	Lanetown Rd						
AAR DOT NO.:	224704E						

2 YEAR

Form complies with FRA S-96-05

1 YEAR

NOMENCLATURE OF DEVICE	TYPE, MODEL, OR CSX REFERENCE NUMBER	CSX SOC NUMBER	MFR	SERIAL NUMBER	RESISTANCE	NEUTRAL			POLAR PICKUP WORKING			IZING	₩			
						DROPAWAY	PICKUP	WORKING	Ţ	REVERSE	NORMAL	REVERSE	PERCENT ON TIME	DATE MM/DD/YY	RESULT/ CONDITION LEFT	ITEM ADJUSTEI OR REPLACED
XR	В			80187874	500	0.006	0.011	0.012						5/22/2015	С	
GPR	В			8005332	194	0.0065	0.0115	0.0115						5/22/2015	С	
XGR	В			9892253	194	0.005	0.0299	0.03						5/22/2015	С	
EOR	В			9892771	60	0.038	0.093	0.093						5/22/2015	С	
												Signatur	e of E	mployee Performi	ng Test (in ink)	

See instructions on reverse